
Instruction Manual



24-05-V2-172

Product Description

This product is a digital thermo-hygrometer that combines temperature humidity sensors to provide real-time monitoring of Temperature and Humidity on its digital LCD display.
It is easy to operate, quality assured and worth buying.



How To Use

1.Turn On:

a) Opening the back bracket and installing the battery, the device will start to work.


b) You can place the device on the desktop or other flat positions.

2.Install Battery:

a) Open the battery slot cover;

b) Install the battery in the correct positive and negative directions;

c) Close the battery slot cover.



3.Temperature Unit:

a) Single-press **Temperature Unit Switch Button** to switch the temperature unit between Celcius(°C) and Fahrenheit(°F).

Tips:

1. Temperature : When the temperature is lower than -10°C, the reading displays LL.L°C, when the temperature is higher than 50°C, the reading displays HH.H°C.
2. Humidity : When the humidity is lower than 10%RH, the reading displays LL.L%, when the humidity is higher than 90%RH, the reading displays HH.H%.

Product List

Thermo-hygrometer	* 1
Product Manual	* 1

Humidity Level Standard Reference :

	Humidity Level	Average Standard Value
Humidity	DRY	＜41%
	COMFORT	42%-70%
	WET	＞71%

Humidity level indicator



Precautions

1. Keep away from high temperature, strong magnetism, and dusty environment.
2. Please replace the battery in time when the battery is low.
3. This Thermo-hygrometer is for reference of healthy life.

Product Specifications

Item	Thermo-hygrometer
Product Size	93*95*40mm
Product Weight	55g
Display Method	LCD Display
Measuring Item	Temperature, Humidity
Atmospheric Pressure	12.5 PSI- 15.4 PSI
Sampling Time	1.5 Seconds
Operating Voltage	DC 3V
Temperature Range	-10°C-50°C(14°F-122°F)
Storage Temperature	-10°C-60°C(14°F-140°F)
Temperature Accuracy	±0.3°C
Relative Humidity	10%-90%RH
Humidity Range	10%-90%RH
Humidity Accuracy	± 5%RH
Power Supply	1*1.5V AAA Battery (Not Included)